2018 BOND IMPROVEMENTS*



Lakewood Articulation Area

	Buildre	EM SEGUE OF COMPANY	ane properly	abilding in the part of the pa	eilot Granif	scontroda i	Modulio	ding, pod	ries of	oci ettei	Jedare Jedare	efficient winds	orts dood dood leding find field in	ndorenents nteror paint,	Jedate h	ud sinci	abacital appropriate appropria	or and the state of the state o	n knish Onne	Heirot Lidakitenii Pakingli	norotettentis	mprovement	de Liidrette Old Liniture	old called the late of the lat	oordile pariit	one Replace	nets de stelvich	O druithlibs
Belmar Elementary						•	•	•	•		•	•	•	•				•	•	•	•	•	•			•		
Creighton Middle							•	•		•	•			•	•					•			•			•		
Eiber Elementary						•	•	•			•	•	•	•	•		•	•	•	•	•	•			•	•	•	•
Glennon Heights Elementary						•					•			•							•	•	•		•	•	•	
Lakewood High				•				•			•			•	•			•					•			•		•
Slater Elementary						•	•	•			•			•	•					•			•		•	•	•	
South Lakewood Elementary							•	•						•						•		•	•			•		•

*Based on 2018 Capital Improvement Plan. Subject to project scope.

Belmar Elementary School Improvements

- Remove modular buildings.
- Update security cameras & classroom security door hardware.
- Secure building vestibules, entries & office location
- New, more secure exterior doors.
- Update existing technology for student learning.
- Update old electrical wiring, panels & increase capacity.
- Commercial kitchen improvements.
- · Update interior paint, wall coverings.

- Parking lot improvements, sidewalk replacements.
- New paint to protect exterior.
- · New gym & cafeteria flooring.
- New carpet.
- Replace:
- Old student furniture, cafeteria tables & library furniture;
- Old carpet & tile;
- Interior lighting with energy-efficient LFDs: &
- Old playground equipment.



Age of Facility: 57 years (built in 1961)

Square Footage: 40,829

Enrollment: 320

BUILDING CONDITION: FAIR

FCI: 24.8%

FCI is a measurement of the physical condition of the school's interior, exterior & grounds.

> Good: less than 10% Fair: 11% to 30% Poor: greater than 30%.