2018 BOND IMPROVEMENTS*



*Based on 2018 Capital Improvement Plan. Subject to project scope.



Age of Facility: 78 years (built in 1940) Enrollment: 286

Square Footage: 68,612

BUILDING CONDITION: FAIR

FCI: 22.8%

FCI is a measurement of the physical condition of the school's interior, exterior & grounds.

Good: less than 10% Fair: 11% to 30% Poor: greater than 30%.

Brady Exploration School

- Add an elevator to the building.
- Update security cameras & classroom security door hardware.
- Secure building vestibules, entries & office location.
- Update existing technology for student learning.
- Update interior paint, wall-coverings.
- Repair & update exterior finish.
- Update old electrical wiring, panels & increase capacity.

- Update old heating & cooling equipment, plumbing fixtures & piping.
- Replace:
 - Old sink cabinets, overhead shelving & bookcases;
 - Old student furniture, cafeteria tables & library furniture;
 - Interior lighting with energy-efficient LEDs;
 - Old playground equipment; &
 - Old carpet & floor tile.