2018 BOND IMPROVEMENTS*



Bear Creek Articulation Area

	Buildre	an lacillador s	ine property	Addition of the Addition of th	S Gonth Gonth	Stor programs	odulo	ing, por	tiles of a	oco ecure exter	ild doors	deficient winds	one of the state o	proverteart, iterior paint, iterior	Jedate h	ng dinci	Applied Hime	philody all be steed that to go the to the steed that to go the steed that to go the steed that	sterior stelakicheni Paking	ndodenenés	morale mental and control of the con	dd fyrithe Replace	ald differ on the second	ooriile noddle priit	one Replace	net de stelving	antitles and a Reddeenon's
Bear Creek High							•	•		•	•			•	•										•		
Bear Creek K-8							•	•			•			•	•										•		•
Carmody Middle						•	•	•			•		•	•	•			•			•			•	•		•
Green Gables Elementary			•			•	•	•	•	•	•		•	•	•			•	•	•	•	•	•	•	•	•	•
Kendallvue Elementary						•	•	•	•		•			•	•			•		•		•	•	•	•	•	
Kendrick Lakes Elementary	•																										
Peiffer Elementary						•	•	•			•			•	•			•	•	•			•		•		
Red Rocks Elementary							•	•		•	•			•	•			•	•	•	•	•			•	•	•
Westgate Elementary						•	•	•	•		•			•	•			•				•	•	•	•	•	•

*Based on 2018 Capital Improvement Plan. Subject to project scope.

Westgate Elementary School Improvements

- Remove modular buildings.
- · New, more secure exterior doors.
- Update security cameras & classroom security door hardware.
- Secure building vestibules, entries & office
- Update existing technology for student learning.
- · Replace old library furniture.
- Update interior paint, wall-coverings.
- Update old electrical wiring, panels & increase

- Update old heating & cooling equipment, plumbing fixtures & piping.
- · Commercial kitchen improvements.
- Movable partitions with new, sound-proof
- Old sink cabinets, overhead shelving & bookcases;
- Interior lighting with energy-efficient
- Old carpet & floor tile;
- Old ceilings; &
- Worn roofing.



Age of Facility: 46 years (built in 1972)

Square Footage: 51,212

Enrollment: 534

BUILDING **CONDITION: FAIR**

FCI: 28.4%

FCI is a measurement of the physical condition of the school's interior, exterior & grounds.

> Good: less than 10% Fair: 11% to 30% Poor: greater than 30%.